

PONTA MONTADA






























Pontas Montadas - *Uso geral em desbaste, rebarbação, remoção, acabamentos e limpeza de peças.*

Dimensões















Hastes: 3 ou 3,17 mm / 6 ou 6,35 mm / 10 ou 9,52 mm















Comprimento das hastes: de 2 a 200 mm































									
Tipo DxA Haste	A-1 20x65 6,4	A-2 25x30 6,4	A-3 22x70 6,4	A-4 30x30 6,4	A-5 22x30 6,4	A-6 20x30 6,4	A-11 22x45 6,4	A-12 18x30 6,4	A-13 30x30 6,4
									
Tipo DxA Haste	A-14 18x22 6,4	A-15 6x27 6,4	A-21 25x25 6,4	A-22 20x16 6,4	A-23 20x25 6,4	A-24 6x20 6,4	A-25 Diâm. 25 6,4	A-26 Diâm. 16 6,4	A-31 35x25 6,4
									
Tipo DxA Haste	A-32 25x16 6,4	A-33 25x13 6,4	A-34 40x10 6,4	A-35 25x10 6,4	A-36 40x10 6,4	A-37 30x6 6,4	A-38 25x25 6,4	A-39 20x20 6,4	A-40 Diâm.20 6,4

OBS: DxA(DiâmetroxA altura) .Todas as medidas em milímetros

														
Tipo	B-41	B-42	B-43	B-44	B-45	B-46	B-47	B-51	B-52	B-53	B-54	B-55	B-61	B-62
DxA	16x16	13x20	6x8	6x10	5x8	3x8	3x4	12x20	10x20	6x16	6x13	3x6	20x8	13x10
Haste	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2

														
Tipo	B-63	B-64	B-65	B-70	B-71	B-72	B-73	B-74	B-81	B-82	B-83	B-84	B-90	B-91
DxA	6x5	6x1,5	3x3	20x3,0	16x2,5	13x3	13x3	6x2,5	20x5	13x6	10x4	8x5	13x13	13x16
Haste	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2

														
Tipo	B-92	B-93	B-94	B-95	B-96	B-97	B-98	B-101	B-102	B-103	B-104	B-105	B-106	B-111
DxA	6x6	5x5	4x2,5	3x4	3x6	2,5x10	2,5x6	16x18	16x13	16x5	8x10	6x6	3x3	12x18
Haste	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2

														
Tipo	B-112	B-113	B-114	B-115	B-121	B-122	B-123	B-124	B131	B132	B-133	B-134	B-135	B-136
DxA	10x13	6x6	6x10	2,5x3	Diâm.13	Diâm.10	Diâm.5	Diâm.3	13x13	10x13	10x10	8x10	6x13	6x8
Haste	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2

OBS: DxA(DiâmetroxAltura) .Todas as medidas em milímetros



Tipo	C-141	C-142	C-143	C-144	C-145	C-146	C-147	C-148	C-149	C-150	C-151	C-152	C-153	C-154
DxA	2,5x4	2,5x6	3x3	3,2x6	3,2x10	3,2x13	4x0,8	4x1,6	4x6,5	4,8x1,6	5x3	5x6,5	5x10	5x13
Haste	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2
Tipo	C-155	C-156	C-157	C-158	C-159	C-160	C-161	C-162	C-163	C-164	C-165	C-166	C-167	C-168
DxA	5,2x6,5	6,4x0,8	6x2	6x3	6,5x5	6,5x6,5	6,5x8	6,5x10	6,5x13	6x20	8x1,5	8x3	8x6,5	8x8
Haste	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2
Tipo	C-169	C-170	C-171	C-172	C-173	C-174	C-175	C-176	C-177	C-178	C-179	C-180	C-181	C-182
DxA	8x10	8x13	8x20	10x1,5	10x3,2	10x6,5	10x10	10x13	10x20	10x25	10x32	13x0,8	13x1,5	13x3,2
Haste	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2	3,2
Tipo	C-183	C-184	C-185	C-186	C-187	C-188	C-189	C-190	C-191	C-192	C-193	C-194	C-195	C-196
DxA	13x6,5	13x10	13x13	13x20	13x25	13x38	13x50	16x1,5	16x3,2	16x6,5	16x10	16x13	16x20	16x25
Haste	3,2	3,2	3,2	3,2	3,2	6,4	6,4	3,2	3,2	3,2	3,2	3,2	3,2	6,4
Tipo	C-197	C-198	C-199	C-200	C-201	C-202	C-203	C-204	C-205	C-206	C-207	C-208	C-209	C-210
DxA	16x50	16x63	20x1,5	20x3,2	20x6,5	20x10	20x13	20x20	20x25	20x32	20x38	20x50	20x63	22x1,5
Haste	6,4	6,4	3,2	3,2	3,2	3,2	3,2	6,4	6,4	6,4	6,4	6,4	6,4	3,2
Tipo	C-211	C-212	C-213	C-214	C-215	C-216	C-217	C-218	C-219	C-220	C-221	C-222	C-223	C-224
DxA	22x3,2	22x6,5	22x10	24x,5	25x3,2	25x6,5	25x10	25x13	25x20	25x25	25x38	25x50	25x63	25x76
Haste	3,2	3,2	3,2	3,2	3,2	3,2	6,4	6,4	6,4	6,4	6,4	6,4	6,4	9,5
Tipo	C-225	C-226	C-227	C-228	C-229	C-230	C-231	C-232	C-233	C-234	C-235	C-236	C-237	C-238
DxA	32x6,5	32x10	32x13	32x20	32x25	32x32	32x38	32x50	32x63	32x76	38x6,5	38x13	38x25	38x38
Haste	6,4	6,4	6,4	6,4	6,4	6,4	6,4	6,4	9,5	9,5	6,4	6,4	6,4	6,4
Tipo	C-239	C-240	C-241	C-242	C-243	C-244	C-245	C-246						
DxA	38x50	38x63	38x76	50x25	50x38	50x50	50x63	50x76						
Haste	9,5	9,5	9,5	6,4	9,5	9,5	9,5	9,5						

OBS: DxA(DiâmetroxAltura) .Todas as medidas em milímetros.